

FIG. 1

2/10




FIG.2

3/10




FIG. 3A

4/10




FIG.3B

5/10

130

ObdBuf					131
SUPPIDS	Dxbf0fb980				PIDs SUPPORTED
EVLSUP	rcfmrCFM	EOOasehC	eOOasehC		Eval supported/status
MIL			on		MIL light
NUMDTC			1		No. of DTCs
FUEL1			closed		Fuel system status
LOAD			10.2%		Calculated load value
ECT			188 degF		Engine coolant temp
SRFT1			5.5%		Short term fuel trim bank 1
LNGF1			0.8%		Long term fuel trim bank 1
RPM			952 RPM		Engine speed
VSS			24 MPH		Vehicle speed
SPARK			9 deg		Ignition timing (ATDC)
IAT			100 degF		Intake air temp
MAF			5.62 gm/s		Air flow rate
TP			25.5 %		Throttle position
O2SLO	B1S1	B1S2	B2S1	B2S2	O2 sensor location
O2S11				0.0%	O2 bank 1 sensor 1
O2S11V				0.055 V	O2 bank 1 sensor 1
O2S12				100.0 %	O2 bank 1 sensor 2
O2S12V				0.100 V	O2 bank 1 sensor 2
O2S21				3.1 %	O2 bank 2 sensor 1
O2S21V				0.070 V	O2 bank 2 sensor 1
O2S22				100.0 %	O2 bank 2 sensor 2
O2S22V				0.040 V	O2 bank 2 sensor 2
ODO				6175 mi	Odometer
AIR				15541792 gm	Total air mass
LRPM				1711390 Klrpm	Total load*RPM
BATV				14.0 V	Battery (on)
BATVOFF				13.4 V	Battery (off)
RESETS				17	Resets
MANUF				0x02100000	Manuf codes
TRIPS				738	Trips
KEYON				2m 58s-> 176 sec	Keyon time
RUN	12d 5h 5m 55s ->			1055155 sec	Run time
DTC_C				P0743	OBD DTCs
SCHEMA	0x3b901783	GENERIC	v2032		Schema
MPAK_BASE				22	Mobitex base station base ID
MPAK_AREA				39	Mobitex base station area ID
MPAK_RSSI				-79 dBuV	Received signal strength indicator

132

134


136

FIG.4

150

VEHICLE LOCATION

STATUS: YOUR VEHICLE IS PARKED



VEHICLE IS  
PARKED.

VEHICLE LOCATION AS OF 11/08/02 03:24 PM

APPROXIMATE LOCATION:

7770 NORCANYON WAY  
SAN DIEGO, CA 92126 US

NEAREST CROSS STREET:  
LATITUDE/LONGITUDE:

27.03 W NORCANYON WAY & LANDBREEZE WAY  
32.93369 / -117.15584

IGNITION:  
OFF

FIG.5A

7/10




FIG. 5B

8/10




FIG. 6



9/10




FIG.7

10/10




FIG.8